



Original Project Title:

**Carr Lake Watershed / Reclamation
Ditch Subwatershed Assessment and
Management Plan**

Prepared for MCWRA Board of Directors

Funded by The Federal EPA under the Clean
Water Act Section 205j Water Quality Planning
Program as,
SWRCB Grant No. 02-098-250-0 and by
Reclamation Ditch, Zone 9 Benefit
Assessment



The Watershed Institute

Division of Science and Environmental Policy
California State University Monterey Bay
watershed.csUMB.edu

100 Campus Center, Seaside, CA, 93955-8001
831 582 4452 / 4431.

*Central
Coast
Watershed
Studies*

CCoWS

Final Report:

**Monterey County Water
Resources Agency –
Reclamation Ditch
Watershed Assessment and
Management Strategy:**

Part A – Watershed Assessment

Acknowledgements

Report prepared by:

- Joel Casagrande (Watershed Institute, FCSUMB)
- Fred Watson, PhD (Project Leader, Watershed Institute, FCSUMB)
- In conjunction with MCWRA Project Manager and Technical Advisory Committee (listed below)

MCWRA Project Manager:

- Manuel Quezada (MCWRA Project Manager)

Technical Advisory Committee (TAC):

- George Fontes (Comgro Inc.)
- Ross Clark (California Coastal Commission, CCC)
- Amanda Bern (CCRWQCB)
- Bryan Largay (Resource Conservation District of Monterey County RCDMC)
- Traci Roberts (Monterey County Farm Bureau, MCFB)
- Carl Niizawa (City of Salinas)
- Kathleen Thomasberg (MCWRA)

Thanks to the following individuals and agencies. Note that the listing of their names here does not necessarily imply that this report reflects their opinions and/or interpretations.

- Mark Angelo (PE) and Karen Worcester (CCRWQCB)
- Laura Lee Lienk, Restoration Ecologist (CSUMB)
- Doug Smith Ph.D, RG, Geologist/Hydrologist, (CSUMB)
- CCoWS Technicians: Julie Hager, Don Kozlowski, Joy Larson, Wendi Newman
- CSUMB Students: Janna Hameister, Jessica Masek, Morgan Wilkinson
- MCWRA: Curtis Weeks, Richard Boyer, German Criollo, Rob Johnson
- City of Salinas: Denise Estrada, Chuck Lerable, Ron Cole
- Vasiliki Vassil (Soquel Creek Watershed Council and CSUMB)
- Jerry J. Smith Ph.D, Fisheries Biologist, (SJSU)
- John Oliver Ph.D, Wetland Ecologist (MLML)
- Gabilan Cattle Company: The Reeves Family, Darrell Boyle
- Emily Hanson & Melanie Bojanowski, Resource Conservation District of Monterey County (RCDMC)
- Don Roberson, co-author of *Atlas of Breeding Birds of Monterey County* (1993)
- David Suddjian, Local bird expert
- Brian Anderson, Department of Environmental Toxicology, University of California, Davis
- Chris Bunn, Crown Packing Co., Inc.
- Dennis Sites, Agricultural Consultant
- Eric Van Dyke (Geographical Ecologist, Elkhorn Slough National Estuarine Research Reserve)
- Michael Cahn, UC Cooperative Extension

[Page intentionally left blank]

Primary audience

The primary audience of this Assessment and Management Strategy is the stakeholders of the Reclamation Ditch Watershed, and associated education, research, and professional entities:

- Stakeholders
 - Land use communities
 - Row-crop agricultural Community
 - Individual growers & shippers
 - Monterey County Farm Bureau
 - Grower Shipper Association
 - Ranching Community
 - Individual ranchers
 - Gabilan Cattle Company
 - Development Interests
 - Salinas Valley Builders Exchange and equivalent representatives
 - Creek Bridge Homes
 - Environmental/restoration/outreach groups
 - Friends of Tembladero (FOT)
 - Friends of Salinas Creeks (FOSC)
 - Return of the Natives (RON)
 - Monterey Bay National Marine Sanctuary Citizens Monitoring Network
 - Audubon Society Local Chapter
 - Agencies
 - Federal Agencies
 - NOAA Fisheries
 - United States Fish and Wildlife Service (USFWS)
 - Environmental Protection Agency (EPA)
 - Monterey Bay National Marine Sanctuary (MBNMS)
 - State Agencies
 - State Water Resources Control Board (SWRCB)
 - Central Coast Regional Water Quality Control Board (CCRWQCB)
 - California Department of Fish Game (CDFG)
 - California Coastal Commission (CCC)
 - Monterey County Agencies/Districts
 - Monterey County Water Resources Agency (MCWRA)
 - Monterey County Planning Department (MCPD)
 - Monterey County Agricultural Commissioner's Office (MCACO)
 - Resource Conservation District of Monterey County (RCDMC)
 - Moss Landing Harbor District
 - Local Cities and unincorporated Monterey County areas
 - City of Salinas

- Castroville area in unincorporated Monterey County
- Prunedale area in unincorporated Monterey County
- Moss Landing area in unincorporated Monterey County

Educational / professional

- Educational and research groups
 - University California Santa Cruz (UCSC)
 - Moss Landing Marine Labs (MLML)
- Consultants:
 - Schaaf and Wheeler Consulting Civil Engineers (SWCCE)
 - John Gilchrist and Associates/Fall Creek Engineering
 - Hagar Environmental Science (HES)
 - Camp Dressser McGee

Table of Contents

ACKNOWLEDGEMENTS	III
PRIMARY AUDIENCE	V
TABLE OF CONTENTS	VII
LIST OF FIGURES AND TABLES	XI
PROJECT SUMMARY: ASSESSMENT PHASE	1
EXECUTIVE SUMMARY	3
EXECUTIVE SUMMARY OF PART A – WATERSHED ASSESSMENT:	4
1. INTRODUCTION	7
BACKGROUND	7
STUDY AREA	8
<i>Hydrology</i>	8
<i>Climate</i>	9
<i>Geology and Soils</i>	9
<i>Land cover and vegetation</i>	9
2. HISTORICAL CONDITIONS	19
OVERVIEW AND METHODS	19
LAND USE AND POPULATION	20
HYDROLOGY	31
HISTORICAL WILDLIFE	45
3. SOCIO-ECONOMIC CONTEXT	49
INTRODUCTION	49
REGIONAL CONTEXT	49
IMPORTANCE OF RECLAMATION DITCH WATERSHED AGRICULTURE	51
LOCAL IMPORTANCE OF RECLAMATION DITCH WATERSHED AGRICULTURE	55
POPULATION DENSITY IN THE RECLAMATION DITCH WATERSHED	56
4. HYDROLOGY AND CHANNEL CONDITIONS ASSESSMENT	59
OVERVIEW	59
GENERAL HYDROLOGY	59
CHANNEL CONDITIONS	66
FLOODING	80
CHANNEL SEDIMENTATION AND EROSION	85
<i>Perspective</i>	85
<i>Sediment Sources</i>	85
<i>Transport</i>	92
CHANNEL SEDIMENTATION AND ITS MAINTENANCE	93
<i>Channel erosion and its maintenance</i>	98
5. BOTANICAL ASSESSMENT	101
INTRODUCTION	101
RIPARIAN VEGETATION COMMUNITIES	102

<i>Saltwater Marsh Community</i>	104
<i>Freshwater Slough/Wetland and Seasonal Pond Communities</i>	106
<i>Mixed Riparian Community</i>	109
<i>Montane Riparian Community</i>	111
<i>Gabilan Ridgeline and Plateau Communities</i>	112
<i>Non-native Weeds and Grasses</i>	114
DISTRIBUTION OF RIPARIAN TREES IN THE RECLAMATION DITCH WATERSHED	118
DISTRIBUTION OF RARE/LISTED PLANTS AND NATURAL COMMUNITIES	122
6. WATER QUALITY ASSESSMENT	127
OVERVIEW:	127
SPECIFIC BENEFICIAL USES OF THE RECLAMATION DITCH WATERSHED	128
WATER QUALITY OF RECLAMATION DITCH WATERSHED SITES WITHIN REGIONAL CONTEXT	130
<i>CCRWQCB background statements</i>	130
<i>Comparison with CCAMP data from the Salinas Valley sub-region</i>	131
<i>Comparison with CCAMP data from the entire Central Coast Region</i>	131
LEGACY PESTICIDES.....	140
303D LIST OF IMPAIRED WATERBODIES	140
LOCAL WATER QUALITY PUBLICATIONS	143
DATA SUMMARY: PARAMETER ASSESSMENT CARDS (PAC'S).....	144
<i>Suspended Sediment Concentration (SSC)</i>	148
<i>Nutrients</i>	149
<i>Temperature</i>	152
<i>Dissolved Oxygen</i>	153
<i>Bacteria (Fecal Coliform)</i>	154
<i>Pesticides</i>	155
7. BIOLOGICAL ASSESSMENT	161
SUMMARY.....	161
BENTHIC MACROINVERTEBRATES	162
<i>Overview and Methods</i>	162
<i>Water Quality and Physical Habitat</i>	164
FISHERIES	171
<i>General Species Distribution</i>	171
<i>Fish Kills</i>	176
<i>Fish Migration</i>	178
AMPHIBIANS AND REPTILES.....	181
BIRDS.....	188
<i>Overview</i>	188
<i>Spatial distribution of birds in relation to land use</i>	190
MAMMALS	193
DISTRIBUTION OF RARE/LISTED SPECIES	198
8. BIBLIOGRAPHY	199
9. ACRONYMS AND SCIENTIFIC UNITS	207
10. APPENDICES	209
APPENDIX A - STAKEHOLDER COMMENTS	209
APPENDIX B – CHECKLIST OF AMPHIBIANS AND REPTILES	223
APPENDIX C – BREEDING BIRDS.....	225

APPENDIX D – RIPARIAN VEGETATION SPECIES-SITE TABLE..... 229
APPENDIX E - WATER QUALITY DATA 235
APPENDIX F – WATERSHED QUALITY ASSURANCE AND PROJECT PLAN AND MONITORING PLAN:
INVERTEBRATE SAMPLING 277
APPENDIX G – SUBMISSION OF DATA TO STORET DATABASE..... 277

[Page intentionally left blank]

List of Figures and Tables

List of Figures	Page
Chapter 1 Introduction	
Figure 1.1. The Reclamation Ditch Watershed	11
Figure 1.2. The Reclamation Ditch Watershed and the Zone 9 Boundary	12
Figure 1.3. City of Salinas Storm Drain System	13
Figure 1.4. Mean annual air temperature for the Reclamation Ditch Watershed and surrounding area	14
Figure 1.5. Mean annual precipitation for the Reclamation Ditch Watershed and surrounding area	15
Figure 1.6. Surface geology of the Reclamation Ditch Watershed and surrounding area	16
Figure 1.7. Soil texture classification map for the Reclamation Ditch Watershed	17
Figure 1.8. Land use/land cover in the Reclamation Ditch Watershed and surrounding area	18
Chapter 2 Historical Conditions	
Figure 2.1. City of Salinas population grown between 1870 and 2000	20
Figure 2.2. Groundwater elevations in the lower Salinas Valley (1901)	23
Figure 2.3. Summary of irrigated acreage and crops in Monterey and San Benito Counties.	24
Figure 2.4. Urban growth in the Reclamation Ditch Watershed as of 1947 and 1984	26
Figure 2.5. Groundwater elevations in the lower Salinas Valley based on USGS groundwater well data (1970–80’s).	28
Figure 2.6. Changes in seawater intrusion in the pressure 180 ft aquifer	29
Figure 2.7. Changes in seawater intrusion in the pressure 400 ft aquifer	30
Figure 2.8. The Lower Salinas River and Tembladero Slough in 1854.	33
Figure 2.9. The original drainage (circa 1906) of the Lower Reclamation Ditch Watershed including the locations of the natural lakes.	34
Figure 2.10. A map of the proposed improvement of (Lower) Reclamation Ditch Watershed (1906) by Lou Hare, Civil Engineer.	35
Figure 2.11. Estimated annual runoff (acre feet) in 1918 for each of the sub-watershed units of the Reclamation Ditch Watershed.	37
Figure 2.12. The Salinas River Lagoon in 1910.	38
Figure 2.13. The Reclamation Ditch Watershed in 1912.	39
Figure 2.14. Gabilan Creek (between Boronda Rd. and Constitution Blvd.) realignment in the early 1990’s.	42
Figure 2.15. A stretch of Gabilan Creek within the new alignment looking downstream from East Boronda Road.	43
Figure 2.16. A Watershed Institute restoration project at Laurel Pond. Laurel Avenue is shown in the upper right corner.	43
Chapter 3 Socio-economic Context	
Figure 3.1. 2000 Population density by census tract for the Reclamation Ditch Watershed and surrounding areas.	57
Chapter 4 Hydrology and Channel Conditions	
Figure 4.1. Non-perennial vs. artificially perennial flow regimes.	60
Figure 4.2. Locations of major surface water pump stations in the Gabilan Creek Watershed.	62
Figure 4.3. Flow duration curves for each of the two USGS Streamflow Gage sites in the Reclamation Ditch Watershed.	64

Figure 4.4. A comparison of stream flow response to precipitation in Gabilan Creek and the Reclamation Ditch.	65
Figure 4.5. Gabilan Creek in the Mountain plateau zone.	66
Figure 4.6. Stream channel classification and distribution in the Reclamation Ditch Watershed.	66
Figure 4.7. Headwaters of Gabilan Creek in the plateau area near Fremont Peak.	66
Figure 4.8. An in-stream ranch pond on the plateau area south of Fremont Peak State Park.	66
Figure 4.9. The headwaters of Gabilan Creek in the Montane Zone.	67
Figure 4.10. Gabilan Creek at Crazy Horse Canyon Rd in the Foothill Zone.	68
Figure 4.11. Gabilan Creek near at Natividad Road with native sycamore trees, a low-flow channel and primarily sandy substrate – Vegetated Non-perennial Zone.	69
Figure 4.12. Gabilan Creek upstream of Veteran’s Memorial Park in Salinas – Vegetated-perennial Zone.	70
Figure 4.13. A channelized section of Gabilan Creek downstream of Hebert Road – Ditch, Non-perennial Zone.	71
Figure 4.14. A channelized section of lower Alisal Creek near Hartnell Road.	72
Figure 4.15. The Reclamation Ditch upstream of the HWY 183 Bridge – Ditch/Canal, Perennial Zone.	73
Figure 4.16. The Reclamation Ditch at Victor Way in west Salinas – Ditch/Canal Perennial Zone.	74
Figure 4.17. Lower Santa Rita Creek near the Chinn Pump Station.	74
Figure 4.18. Tembladero Slough looking upstream at the confluence of Tembladero Slough (Merritt Lake drainage) with the Reclamation Ditch – Slough (Freshwater) Zone	75
Figure 4.19. The Old Salinas River Channel looking upstream from Potrero Road crossing – Slough (Brackish) Zone.	77
Figure 4.20. Saltwater marsh habitat in Moss Landing Harbor.	77
Figure 4.21. Flooded areas of the Northern Salinas River Valley and Reclamation Ditch Watershed at the peak of the flood on March 12,1995.	79
Figure 4.22. Flooded areas during the March 1995 flood event	80
Figure 4.23. Flooded areas during the March 1995 flood event	80
Figure 4.24. An example of the photos used for the evaluating flood extent on March 15, 1995.	81
Figure 4.25. A comparison of Gabilan Creek stream flow during the 1995 and 1998 storm season.	82
Figure 4.26. Stream bank erosion in Gabilan Creek near Hebert Road.	85
Figure 4.27. A construction site on Davis Road near the Reclamation Ditch.	85
Figure 4.28. Sediment erosion from a strawberry farm on relatively steep land with highly erodible soil.	86
Figure 4.29. Sediment rich agricultural field discharge into Gabilan Creek.	86
Figure 4.30. Bank erosion in the Reclamation Ditch.	87
Figure 4.31. Gully formations along the left bank of the Reclamation Canal.	87
Figure 4.32. Erosion and sediment transport in a roadside ditch near Old Stage Road.	88
Figure 4.33. Road crossings in the creek channel, as shown here, can supply sediment to the stream channel during winter and summer.	88
Figure 4.34. Soil erodibility potential in the Reclamation Ditch Watershed	89
Figure 4.35. Bedload yield per unit area of watershed at sampling sites extending from Gabilan Creek into the Reclamation Ditch (from Watson et al., 2003).	92
Figure 4.36. MCWRA right-of-way and maintenance easements in the Reclamation Ditch System.	95
Figure 4.37. Areas and frequency of silt removal and maintenance within the Reclamation Ditch system and lower Gabilan Creek conducted by MCWRA and the City of Salinas.	96
Figure 4.39. Areas within the study area that are currently maintained for stream bank erosion by Monterey County Water Resources Agency.	98

Chapter 5 Botanical Assessment

Figure 5.1. Vegetation communities within the riparian zone of the Reclamation Ditch Watershed	103
Figure 5.2. Pickleweed salt marsh.	104
Figure 5.3. Pickleweed, with the invasive ice-plant immediately above.	105
Figure 5.4. The Old Salinas River Channel near Potrero Rd (right bank).	106
Figure 5.5. Freshwater slough/wetland habitat in Alisal Slough.	107
Figure 5.6. Freshwater slough/wetland habitat in Markley Swamp.	107
Figure 5.7. Espinosa Lake, one of the historic lakes of the Salinas area.	108
Figure 5.8. Mixed riparian vegetation consisting of willow and sycamore trees with an understory of mixed native and non-native vegetation growing along Gabilan Creek near Natividad Road.	110
Figure 5.9. Typical understory species found within the mixed riparian community at Towne Creek.	110
Figure 5.10. Montane riparian vegetation in upper Gabilan Creek.	111
Figure 5.11. Big-leaf maple and sycamore leaves lying in Gabilan Creek.	112
Figure 5.12. Deciduous blue oaks in dense fog at Fremont Peak State Park.	113
Figure 5.13. Oak-savanna habitat along the ridgeline plateau of the Gabilan Range.	113
Figure 5.14. Barren riparian zone on Alisal Slough (only a few scattered tules are present).	116
Figure 5.15. Non-native weeds, both annual and perennial varieties, dominate the banks of the Reclamation Ditch.	116
Figure 5.16. Cape ivy displacing a cottonwood tree in the riparian zone of Gabilan Creek near Crazy Horse Canyon Road.	117
Figure 5.17. Non-native grasses and Monterey Pine trees are the only vegetation found on the banks of the Reclamation Ditch near Airport Rd.	117
Figure 5.18. Distribution of riparian trees in the Reclamation Ditch Watershed.	119
Figure 5.19. Erosion along Vierra Creek (a tributary to Gabilan Creek) has resulted in bare channel banks.	120
Figure 5.20. Cattle grazing in Alisal Creek.	120
Figure 5.21. Removal of streamside vegetation at Towne Creek.	121
Figure 5.22. Occurrence of endangered and threatened listed species, as well as species of concern in the Reclamation Ditch Watershed.	124
Figure 5.23. Unique natural communities within the Reclamation Ditch Watershed and surrounding areas.	125
Chapter 6 Water Quality Assessment	
Figure 6.1. Mean nitrate ($\text{NO}_3\text{-N}$) concentrations at CCAMP sites throughout the Central Coast Region 3.	135
Figure 6.2. Mean unionized ammonia ($\text{NH}_3\text{-N}$) concentrations at CCAMP sites throughout the Central Coast Region	136
Figure 6.3. Mean phosphate concentrations ($\text{PO}_4\text{-P}$) at CCAMP sites throughout the Central Coast Region	137
Figure 6.4. Mean total suspended sediment (TSS) concentrations at CCAMP sites throughout the Central Coast Region	138
Figure 6.5. Mean Fecal Coliform concentrations at CCAMP sites throughout the Central Coast Region	139
Figure 6.6. Section 303(d) listings for various water bodies within and downstream of the Reclamation Ditch Watershed.	143
Figure 6.7. Water quality sampling sites in the Reclamation Ditch Watershed.	147
Figure 6.8. An assessment of suspended sediment concentrations (SSC) in the Reclamation Ditch Watershed.	149
Figure 6.9. An assessment of nitrate concentrations ($\text{NO}_3\text{-N}$) in the Reclamation Ditch Watershed	150
Figure 6.10. An assessment of ammonia concentrations ($\text{NH}_3\text{-N}$) in the Reclamation Ditch Watershed	151
Figure 6.11. An assessment of orthophosphate concentrations ($\text{PO}_4\text{-P}$) in the Reclamation Ditch Watershed	152
Figure 6.12. An assessment of water temperature in the Reclamation Ditch Watershed	153

Figure 6.13. An assessment of minimum dissolved oxygen concentrations in the Reclamation Ditch Watershed	154
Figure 6.14. An assessment of fecal coliform in the Reclamation Ditch Watershed	155
Figure 6.15. Total applied Diazinon: pounds of active ingredient (AI) for 2002	157
Figure 6.16. An assessment of TPC Diazinon concentrations in the lower Reclamation Ditch Watershed.	158
Figure 6.17. Total applied Chlorpyrifos: pounds of active ingredient (AI) for 2002	159
Figure 6.18. An assessment of TPC Chlorpyrifos concentrations in the Lower Reclamation Ditch Watershed	160
Chapter 7 Biological Assessment	
Figure 7.1. BMI sampling locations in the Reclamation Ditch Watershed.	163
Figure 7.2. BMI taxa richness for all sites in the Reclamation Ditch Watershed	169
Figure 7.3. BMI taxa richness as a function of channel substrate.	170
Figure 7.4. BMI taxa richness as a function of water temperature	170
Figure 7.5. Fish assemblages of the Reclamation Ditch Watershed	172
Figure 7.6. A dead carp in the Reclamation Ditch at San Jon Road bridge. October 21, 2003	177
Figure 7.7. Dead carp on the spill way at San Jon Rd.	177
Figure 7.8. A 30" adult gravid female steelhead found dead in Gabilan Creek on March 6, 2004.	178
Figure 7.9. The concrete spill way where an adult female steelhead was found in March 2004.	180
Figure 7.10. A hydrograph for daily mean stream flow in Gabilan Creek and the Reclamation Ditch during the February and March events	180
Figure 7.11. A red-legged frog in a ranch pond near Fremont Peak State Park	183
Figure 7.12. A second red-legged frog warming up in the afternoon sun.	183
Figure 7.13. This juvenile western toad was found in Gabilan Creek near Lexington Drive.	185
Figure 7.14. Western fence lizard along the bank of Gabilan Creek.	185
Figure 7.15. Pacific ring-necked snake	186
Figure 7.16. Gopher snake.	186
Figure 7.17. Great blue heron and Great white egret.	189
Figure 7.18. White pelicans in the Old Salinas River Channel near Potrero Road Tide Gates.	189
Figure 7.19. Canada goose	189
Figure 7.20. A ranch pond – habitat for birds, amphibians, and reptiles.	190
Figure 7.21. Estimated total number of breeding bird species per 4 km ² area (effort-corrected to nominal 50-hours of observation per area)	192
Figure 7.22. Coyote.	195
Figure 7.23. Mule, or black-tailed deer	195
Figure 7.24. Black-tailed Jackrabbits.	195
Figure 7.25. Current areas of significant open space and habitat for larger mammals in the Reclamation Ditch Watershed and surrounding areas (shaded green).	196
Figure 7.26. Occurrence of endangered and threatened listed species, as well as species of concern in the Reclamation Ditch Watershed.	197

List of Tables	Page
Chapter 1 Introduction	
Table 1.1. Estimated area of major land cover types within the Reclamation Ditch Watershed. Boldface indicates primary data, normal typeface indicates derived data.	10
Chapter 2 Historical Conditions	
Table 2.1. Extinct and extirpated species (both locally and statewide), which were previously documented	46

in the northern Salinas Valley.

Chapter 3 Socio–Economic Context

Table 3.1. Estimated agricultural statistics for the Reclamation Ditch Watershed, and its geographic context. 53

Table 3.2. The fifteen largest employers in Monterey County in 2002. Boldface represents employers directly related to the agriculture industry. 55

Chapter 4 Hydrology and Channel Conditions

Chapter 5 Botanical Assessment

Table 5.1. Common non–native weeds and grasses and habitat concerns in the Reclamation Ditch Watershed. 115

Table 5.2. Threatened and endangered plant species occurring in the Reclamation Ditch Watershed and surrounding area. 123

Chapter 6 Water Quality Assessment

Table 6.1. Beneficial Uses that apply to waterways of the Watershed (Basin Plan 1994) 129

Table 6.2. Water quality rankings for Reclamation Ditch Watershed sites and waterbodies relative to sites throughout the Salinas Valley sub–region. – based on CCAMP data 1999–2000. 133

Table 6.3. CCAMP watershed codes. 140

Table 6.4. Bibliography (not complete) for water quality documents of the Northern Salinas Valley area. 144

Table 6.5. Water Quality Monitoring Sites 148

Chapter 7 Biological Assessment

Table 7.1. Site specific water quality and physical habitat features during BMI sampling 164

Table 7.2. Benthic macroinvertebrates collected in the Reclamation Ditch Watershed 167

Table 7.3. Fish species observed in the Reclamation Ditch Watershed and the location(s) of the observation(s). 173

Table 7.4. Species of amphibian and reptile observed in the Reclamation Ditch Watershed 182

[Page intentionally left blank]